

PROTECTIVE CURTAINS, PADS, BLANKETS, CUFFS AND SIMILAR ARTICLES FOR PROTECTION OF TECHNOLOGICAL EQUIPMENTS

Manufacturer: GoodPRO, s.r.o., Dukelská 1247, 334 01 Přeštice, Česká republika www.goodpro.cz

Material:

Aramid; glass and silicate fabrics; FR cotton

Description:

Protective curtains, pads, blankets, cuffs and similar articles for protection of technological equipment against heat and for ancillary works.

Products are made in the following versions:

1. one-layer construction- products are made only of one layer of fabric
2. multi-layer construction- products are made from two or more layers of fabric
3. multi-layer construction with insulating layer - products are made from two or more layers of fabric with insulating layer
4. cuffs, bellows- divided and undivided

Sewing:

Kevlar, cotton with steel fiber

Holding of curtains, pads and blankets:

steel rings, cords, tapes

Protective function:

Products provide the protection against radiant heat, melt-spraying. The main characteristic of this fabric is that, the material of fabrics being exposed to fire or burning particles carbonizes but the fire doesn't spread further. It is necessary to consult the selection of products or materials with safety manager or with the producer.

Use:

The products can be used in the plants where is needed to protect technological equipment against heat and for ancillary works, for example : foundries, engineering, gas industry, glass factory, welding. Terms of using can't be exactly determined, it is necessary to be careful during using.

Temperature limit of the fabrics:

Type	Material	Weight (g/m ²)	Temperature limit (°C)
TEX 350	FR cotton	350	160
A600	Aramid	600	400
A370AL	Aluminized aramid	490	400
Thermoglass	glass + silicone-coated	490	500
640/100 C	glass + carbon	720	600
isoTHERM 800	glass	1250	800
isoTHERM 1000	glass	1200	1000
Silica	Silicate	1100	1100

This temperature limit is for a short-time using.



Maintenance:

These products don't wash, do not bleach, do not iron, don't dry clean, do not tumble dry. Any dirt can be carefully taken away by mechanical way, for example brushing (without aluminized and glass fabrics).

Storage:

Store in dry and well-ventilated areas away from direct sunlight and UV rays. Protect from any damage.

Notes:

Keep the products clean otherwise it can lead to the degradation of its properties. Check after every use. To ensure the greatest possible protection do not make any alternations to the product and/or its design. The product keeps its protective features only in the environment with standard volume of oxygen. Manufacturer does not warrant nor shall manufacturer be liable, or in any way responsible, for damages to a product caused by abuse (including, but not limited to, improper use, lack of reasonable care and maintenance and/or any alteration). In case of any questions, please contact the manufacturer—info@goodpro.cz.